




ASSEMBLY INSTRUCTION


NC*FXX & NC*MXX | XLR Cable Connector

A




A Slide the boot onto the cable.

B




B Prepare cable as shown.

C




C Insert wires into the terminals and solder them.

D




D Put chuck onto the cable.
Attention: Pay attention to the guiding key.

E



E Slide insert and chuck together into the housing.

F



F Finish the installation by turning the bushing onto the connector.

ORDER OF ASSEMBLY

NC * FXX



bushing



chuck



insert



housing

NC * MXX



NEUTRIK AG LI T: +423 / 237 24 24 F: +423 / 232 53 93
 NEUTRIK Zürich AG CH T: +41 44 / 736 5010 F: +41 44 / 736 5011
 NEUTRIK USA Inc. USA T: +1 732 / 901 9488 F: +1 732 / 901 9608
 NEUTRIK (UK) Ltd. UK T: +44 1983 / 811 441 F: +44 1983 / 811 439

NEUTRIK Vertriebs GmbH DE/NL/AT T: +49 8131 / 280 890 F: +49 8131 / 280 830
 NEUTRIK France FR T: +33 1 / 4131 6750 F: +33 1 / 4131 0511
 NEUTRIK Tokyo Ltd. JP T: +81 3 / 3663 4733 F: +81 3 / 3663 4796
 NEUTRIK Hong Kong Ltd. HK T: +852 / 2687 6055 F: +852 / 2687 6052

Draft. Nr.: BDA 158 / 3102M1381 | Update: 12..03.2008 | Data subject to change without prior notice. ©2008NEUTRIK®. ALL RIGHTS RESERVED.

www.neutrik.com

NEUTRIK